



Prairieville Township  
T 1 N R 10 W  
Barry County  
Michigan



Section 33 grid table with numbers 1-36 in a 6x6 arrangement.

Section 33  
08-12-033-  
Scale 1" = 400'



October 1996  
Revised May 1998  
Revised September 2000  
Revised August 2002  
Revised November 2003  
Revised January 2005  
Revised April 2006  
Revised May 2008

This tax map was compiled for tax administration purposes from county and township records. It does not represent a land survey. Barry County Land Information Services 220 West State Street, Hastings MI 49058 (269) 945-1292 or http://www.barrycounty.org/

All dimensions are from tax roll unless noted below.  
D = deeded M or S = surveyed  
SR = Surveyor's Record prior to 1915  
CR = County Record Land Office circa. 1830  
CRONKHITE STEVEN RAY LYNNE 11.9

08-12-033-002-05 first exception has point of beginning error. See R#1066351 for exception, vesting quit claim deed in R#1059507 is particularly vague.

08-12-033-006-30 has the course bearings trimmed off, correction reads from survey in L.1-1 & quit claim in R#1121799  
08-12-033-006-50 has the course bearings trimmed off, correction reads from survey in L.1-1 & warranty deed in R#1095131  
08-12-033-006-40 has the course bearings trimmed off, correction reads from survey in L.1-1 & quit claim in R#1042046  
08-12-033-006-45 has the course bearings trimmed off, correction reads from survey in L.1-1.  
08-12-033-006-20 has the course bearings trimmed off, correction reads from survey in L.1-1.  
GAP between 006-10 & 006-20 owned by William & Ada Petro in L.334-528 and not sold to Welch in L.342-191.

08-12-033-003-11 has one typo, change "N 89D 39M W" to "N89°39'09\"W".  
08-12-033-003-10 should not include lake which is not on the original patent. It is also missing a measure and has a typo in the first call. See split #041201 for typo fix.  
08-12-033-003-16 is missing a measure to point of beginning and should not include land underneath the lake which is not on the original patent  
08-12-033-003-12 is missing bearing in last course, change "TH E PARALLEL WITH TH N LINE OF SD SEC, 414 FT TO THE POB" to "TH S89°39'09\"E 414FT TO POB"  
08-12-033-003-15 has a typo in first course and should not include land underneath the lake which is not on the original patent.  
08-12-033-004-00 is missing some course bearings and should not include land underneath lake which is not on the original patent.

08-12-033-015-00 the figure of 8 rods should be 8 8/9 rods as on deed in L.283-12.

