


Prairieville Township
T 1 N R 10 W
Barry County
Michigan

| | |
|-------------------|-------|
| Gap | |
| Overlap | |
| Address | 12345 |
| Real Property | |
| Personal Property | |
| Approved Split | |
| Plat | |
| Condominium | |
| Mobile Home Park | |



| | | | | | |
|----|----|----|----|----|----|
| 1 | 2 | 3 | 4 | 5 | 6 |
| 7 | 8 | 9 | 10 | 11 | 12 |
| 13 | 14 | 15 | 16 | 17 | 18 |
| 19 | 20 | 21 | 22 | 23 | 24 |
| 25 | 26 | 27 | 28 | 29 | 30 |
| 31 | 32 | 33 | 34 | 35 | 36 |

Section 36
08-12-036-
Scale 1"= 400'



October 1996
Revised May 1998
Revised September 2000
Revised August 2002
Revised November 2003
Revised January 2005
Revised April 2006
Revised May 2008

All dimensions are from tax roll unless noted below.
D = deeded M or S = surveyed
SR = Surveyor's Record prior to 1915
GLO = Government Land Office circa. 1830

08-12-036-011-00 has been surveyed for split #021211.
08-12-035-006-00 is a giant mess with overlaps onto unapproved splits which are landlocked.

08-12-036-008-00 has been surveyed in L.1-183.
08-12-036-001-00 is missing its second measures off the bearings and has been surveyed in L.1-183.
08-12-036-001-10 is missing its second measures off the bearings and has been surveyed in L.1-183.
08-12-036-001-30 is missing its second measures off the bearings and has been surveyed in L.1-183.
08-12-036-001-31 is missing its second measures off the bearings and has been surveyed in L.1-183.
08-12-036-001-40 is missing its second measures off the bearings and has been surveyed in L.1-183.

08-12-050-004-00 overlaps 005-00 and does not indicate any property outside of the plat on the deed.
08-12-050-005-00 needs to include gap parcel. See R#1021014.

08-12-420-011-00 describes part of platted road which has not been vacated.



08-12-036-081-00 should include gap parcel to south as per R#1030162.

08-12-036-050-00 measure of 110.72 feet should be 110.22 feet.