

08-10-011-135-00 needs to include gap parcel to the west and should read as resurveyed for property line adjustment and quit-claims among Shilton, Varney, Kent & Hawkins. See parcel 1 & 3 of split #041004

08-10-011-136-00 is missing its course bearings and dimensions are rounded off. See parcel 2 of split #041004

08-10-011-090-00 overlaps 110 and needs to be described as surveyed for parcels A&B of split #011006.

08-10-011-100-00 overlaps 110, 130 & 135 and should be described as remainder of splits #011004 & #011006.

08-10-011-109-00 is missing its course bearings and should be described as surveyed for split #011004.

08-10-011-139-00 is missing its course bearings and needs to be described as surveyed for split #031003.

08-10-011-140-00 needs to exclude 139 as surveyed with course bearings and new split in R#1163554.

08-10-011-045-00 is missing original parcel entirely now, incorrect point of beginning and errors in bearing. See deed R#1149193.

08-10-011-040-00 needs to include gap parcel to the north that was with this parcel prior to split to 035.

08-10-011-035-00 has an incorrect measure and does not exclude 050. See deed R#1106595.

08-10-011-079-00 is missing its course bearings as surveyed for split #051008.

08-10-011-065-00 has a kink on the west line and needs to be described as deeded in R#1137387 with course bearings.

08-10-011-069-00 overlaps 070 as described because it is missing its course bearings and needs to be described as surveyed for parcel B of split #051012.

08-10-011-070-00 overlaps 069, 074 & 079 and those exceptions have been surveyed for splits #011005, #041009 & #051008

08-10-011-076-00 is missing its course bearings and has been surveyed for split #011005

08-10-011-075-00 is missing bearings has been surveyed for split #011005.

08-10-011-074-00 is missing its course bearings and needs to be described as surveyed for split #041009.

08-10-011-066-00 needs to be described as deeded in R#1135161 with course bearings.